

# MAINTENANCE OFFICE

946 Pisgah Church Road  
Lexington, SC 29072



Floor Area

43,470 SF

## OVERALL ANALYSIS

Maintenance facility is in need of partial roof replacement.

### MAJOR CONCERNS

- Partial roof replacement

### RECOMMENDATIONS

#### ADDITIONS

**\$ 0**

- None

#### RENOVATIONS

**\$ 140,000**

- Roof replacement

#### SAFETY / SECURITY

**\$ 0**

- None

**TOTAL PROJECTED COST**

**\$ 140,000**